

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

IV1283  
ENE  
> 1  
1.643 mi.  
8675 ft.

Site 2 of 2 in cluster IV

Relative:  
Higher

Actual:  
12 ft.

UST:

Name: OCEAN AVENUE GAS CORP  
Address: 3010 OCEAN AVENUE  
City,State,Zip: BROOKLYN, NY 11235  
  
Id/Status: 2-277509 / Active  
Program Type: PBS  
Region: STATE  
DEC Region: 2  
Expiration Date: 07/10/2022  
UTM X: 588892.16976  
UTM Y: 4493514.01231  
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 11993  
Affiliation Type: Facility Owner  
Company Name: SPARTAN PETROLEUM CORP.  
Contact Type: PROPERTY MANAGER  
Contact Name: JAY SEMELMACHER  
Address1: 3333 NEW HYDE PARK ROAD, SUITE 201  
Address2: Not reported  
City: NEW HYDE PARK  
State: NY  
Zip Code: 11042  
Country Code: 001  
Phone: (516) 365-8700  
EMail: JZ@SPARTANPETRO.COM  
Fax Number: Not reported  
Modified By: DAFRANCI  
Date Last Modified: 2019-03-07

Site Id: 11993  
Affiliation Type: Mail Contact  
Company Name: SPARTAN PETROLEUM CORP  
Contact Type: Not reported  
Contact Name: JAY SEMELMACHER  
Address1: 3333 NEW HYDE PARK ROAD  
Address2: SUITE 201  
City: NEW HYDE PARK  
State: NY  
Zip Code: 11042  
Country Code: 001  
Phone: (516) 365-8700  
EMail: JZ@SPARTANPETRO.COM  
Fax Number: Not reported  
Modified By: DAFRANCI  
Date Last Modified: 2019-03-07

Site Id: 11993  
Affiliation Type: Facility Operator  
Company Name: OCEAN AVENUE GAS CORP  
Contact Type: Not reported  
Contact Name: STEVEN SCIARRINO

NY UST  
NY Spills  
RCRA NonGen / NLR  
US AIRS  
FINDS  
ECHO

1000555869  
NYD986984169

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (718) 891-9311  
EMail: Not reported  
Fax Number: Not reported  
  
Modified By: TLRIDNER  
Date Last Modified: 2017-02-24

Site Id: 11993  
Affiliation Type: Emergency Contact  
Company Name: SPARTAN PETROLEUM CORP  
Contact Type: Not reported  
Contact Name: JAY SEMELMACHER  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (516) 993-4750  
EMail: Not reported  
Fax Number: Not reported  
Modified By: DAFRANCI  
Date Last Modified: 2019-03-07

Tank Info:

Tank Number: 001  
Tank ID: 155362  
Tank Status: In Service  
Material Name: In Service  
Capacity Gallons: 4000  
Install Date: 10/01/1991  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Equivalent technology  
Material Code: 2712  
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21  
Date Test: 03/08/2018  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TLYE  
Last Modified: 03/12/2018

Equipment Records:

B04 - Tank External Protection - Fiberglass  
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)  
I02 - Overfill - High Level Alarm  
K01 - Spill Prevention - Catch Basin  
L09 - Piping Leak Detection - Exempt Suction Piping  
E04 - Piping Secondary Containment - Double walled UG  
A00 - Tank Internal Protection - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring  
C02 - Pipe Location - Underground/On-ground  
F04 - Pipe External Protection - Fiberglass  
J02 - Dispenser - Suction Dispenser  
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 001-A  
Tank ID: 155363  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Number: 002  
Tank ID: 155372  
Tank Status: In Service  
Material Name: In Service  
Capacity Gallons: 4000  
Install Date: 10/01/1991  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Equivalent technology  
Material Code: 2712  
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34  
Date Test: 03/08/2018  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: KXLIU  
Last Modified: 12/11/2019

Equipment Records:

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

E04 - Piping Secondary Containment - Double walled UG  
J01 - Dispenser - Pressurized Dispenser  
B04 - Tank External Protection - Fiberglass  
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)  
I02 - Overfill - High Level Alarm  
  
K01 - Spill Prevention - Catch Basin  
A00 - Tank Internal Protection - None  
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring  
L99 - Piping Leak Detection - Other  
L07 - Piping Leak Detection - Pressurized Piping Leak Detector  
C02 - Pipe Location - Underground/On-ground  
F04 - Pipe External Protection - Fiberglass  
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 002-A  
Tank ID: 155373  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Number: 003  
Tank ID: 155375  
Tank Status: In Service  
Material Name: In Service  
Capacity Gallons: 4000  
Install Date: 10/01/1991  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Equivalent technology  
Material Code: 2712  
Common Name of Substance: Gasoline/Ethanol

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Tightness Test Method: 21  
Date Test: 03/08/2018  
Next Test Date: Not reported  
  
Pipe Model: Not reported  
Modified By: TLYE  
Last Modified: 03/12/2018

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG  
B04 - Tank External Protection - Fiberglass  
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)  
I02 - Overfill - High Level Alarm  
K01 - Spill Prevention - Catch Basin  
L09 - Piping Leak Detection - Exempt Suction Piping  
A00 - Tank Internal Protection - None  
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring  
C02 - Pipe Location - Underground/On-ground  
F04 - Pipe External Protection - Fiberglass  
J02 - Dispenser - Suction Dispenser  
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 003-A  
Tank ID: 155376  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None  
I00 - Overfill - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Number: 004  
Tank ID: 155378  
Tank Status: In Service  
Material Name: In Service  
Capacity Gallons: 4000  
Install Date: 10/01/1991

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Equivalent technology  
Material Code: 2712  
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34  
Date Test: 03/08/2018  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: KXLIU  
Last Modified: 12/11/2019

Equipment Records:

B04 - Tank External Protection - Fiberglass  
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)  
I02 - Overfill - High Level Alarm  
K01 - Spill Prevention - Catch Basin  
A00 - Tank Internal Protection - None  
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring  
L99 - Piping Leak Detection - Other  
E04 - Piping Secondary Containment - Double walled UG  
J01 - Dispenser - Pressurized Dispenser  
L07 - Piping Leak Detection - Pressurized Piping Leak Detector  
C02 - Pipe Location - Underground/On-ground  
F04 - Pipe External Protection - Fiberglass  
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 004-A  
Tank ID: 155389  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Tank Number: 005  
Tank ID: 155390  
Tank Status: In Service  
Material Name: In Service  
Capacity Gallons: 4000  
Install Date: 10/01/1991  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Equivalent technology  
Material Code: 2712  
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21  
Date Test: 03/08/2018  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TLYE  
Last Modified: 03/12/2018

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG  
B04 - Tank External Protection - Fiberglass  
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)  
I02 - Overfill - High Level Alarm  
K01 - Spill Prevention - Catch Basin  
L09 - Piping Leak Detection - Exempt Suction Piping  
A00 - Tank Internal Protection - None  
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring  
C02 - Pipe Location - Underground/On-ground  
F04 - Pipe External Protection - Fiberglass  
J02 - Dispenser - Suction Dispenser  
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 005-A  
Tank ID: 155391  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

I00 - Overfill - None  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Number: 006  
Tank ID: 155395  
Tank Status: In Service  
Material Name: In Service  
Capacity Gallons: 1000  
Install Date: 10/01/1991  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Equivalent technology  
Material Code: 0022  
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: 21  
Date Test: 03/28/2002  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: DMPOKRZY  
Last Modified: 07/20/2017

Equipment Records:

C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
J00 - Dispenser - None  
B04 - Tank External Protection - Fiberglass  
E00 - Piping Secondary Containment - None  
I02 - Overfill - High Level Alarm  
K01 - Spill Prevention - Catch Basin  
A00 - Tank Internal Protection - None  
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring  
D00 - Pipe Type - No Piping  
L00 - Piping Leak Detection - None  
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 006-A  
Tank ID: 155396  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None  
I00 - Overfill - None  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Number: 007  
Tank ID: 14090  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None

Tank Number: 008  
Tank ID: 14091  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
H00 - Tank Leak Detection - None  
I00 - Overfill - None

Tank Number: 009  
Tank ID: 14092  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
H00 - Tank Leak Detection - None  
I00 - Overfill - None

Tank Number: 010  
Tank ID: 14093  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Number: 011  
Tank ID: 14094  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 03/01/1962  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Number: 012  
Tank ID: 14095  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 12/01/1991

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
G00 - Tank Secondary Containment - None  
J03 - Dispenser - Gravity

Tank Number: 013  
Tank ID: 14096  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 4000  
Install Date: 10/01/1971  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0009  
Common Name of Substance: Gasoline

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
A00 - Tank Internal Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Number: 014  
Tank ID: 14097

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 08/01/1954  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 9999  
Common Name of Substance: Other

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None  
G00 - Tank Secondary Containment - None  
D00 - Pipe Type - No Piping  
J03 - Dispenser - Gravity  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None

Tank Number: 015  
Tank ID: 14098  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 550  
Install Date: 08/01/1954  
Date Tank Closed: 12/01/1991  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
D00 - Pipe Type - No Piping  
J03 - Dispenser - Gravity  
H00 - Tank Leak Detection - None  
I00 - Overfill - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

SPILLS:

Name: OCEAN AVENUE GAS CORP  
Address: 3010 OCEAN AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1214822 / 2013-07-23  
Facility ID: 1214822  
Facility Type: ER  
DER Facility ID: 433387  
Site ID: 478089  
DEC Region: 2  
Spill Cause: Storm  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2012-11-10  
Investigator: SFRAHMAN  
Referred To: Not reported  
Reported to Dept: 2012-12-17  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Federal Government  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: Not reported  
Remediation Phase: 0  
Date Entered In Computer: 2013-01-22  
Spill Record Last Update: 2013-07-23  
Spiller Name: JAY SEMELMACHER  
Spiller Company: OCEAN AVENUE GAS CORP  
Spiller Address: 3010 OCEAN AVENUE  
Spiller Company: 999  
Contact Name: JAY SEMELMACHER  
DEC Memo:

"Sandy LUST Spills found by EPA \*\* This spill report was created for tracking purposes related to the Department's Hurricane Sandy emergency response efforts.\*\*\*"

Remarks: "ProgNo2-277509 ProgFacNamOCEAN AVENUE GAS CORP Address13010 OCEAN AVENUE LocalityBROOKLYN EmergencyContactJAY SEMELMACHER

EmergPhone(516) 993-4750 AgencyUSEPA ACT Visit11/10/12 Is Facility OperatingYes Was the facility flooded?Yes Is the facility flooded now?Unknown Have there been any spills?Yes If there were spills, were they reported to the NYS Spill Hotline?No Spill Number?NA Is product missing from any tank (based upon inventory records)?No Does the facility have power?Yes If no power, a generator?NA Was there any storm damage to facility?Yes Is there water in any tank?No Was there any storm damage to tank systems?No Follow up RequiredYes InspectorZafonte CommentsNo RD; visible signs of contamination; water in the sump; no apparent water in tanks; dispenser repaired; 2' water" Not reported

All Materials:

Site ID: 478089  
Operable Unit ID: 1227871  
Operable Unit: 01  
Material ID: 2225429  
Material Code: 0064A  
Material Name: unknown material  
Case No.: Not reported  
Material FA: Other

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Quantity: .01  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported

Name: OCEAN AVENUE GAS CORP  
Address: 3010 OCEAN AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1214822 / 2013-07-23  
Facility ID: 1214822  
Facility Type: ER  
DER Facility ID: 433387  
Site ID: 478089  
DEC Region: 2  
Spill Cause: Storm  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2012-11-10  
Investigator: SFRAHMAN  
Referred To: Not reported  
Reported to Dept: 2012-12-17  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Federal Government  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: Not reported  
Remediation Phase: 0  
Date Entered In Computer: 2013-01-22  
Spill Record Last Update: 2013-07-23  
Spiller Name: JAY SEMELMACHER  
Spiller Company: OCEAN AVENUE GAS CORP  
Spiller Address: 3010 OCEAN AVENUE

Spiller Company: 999  
Contact Name: USEPA  
DEC Memo: "Sandy LUST Spills found by EPA \*\* This spill report was created for tracking purposes related to the Department's Hurricane Sandy emergency response efforts.\*\*\*"

Remarks: "ProgNo2-277509 ProgFacNamOCEAN AVENUE GAS CORP Address13010 OCEAN AVENUE LocalityBROOKLYN EmergencyContactJAY SEMELMACHER EmergPhone(516) 993-4750 AgencyUSEPA ACT Visit11/10/12 Is Facility OperatingYes Was the facility flooded?Yes Is the facility flooded now?Unknown Have there been any spills?Yes If there were spills, were they reported to the NYS Spill Hotline?No Spill Number?NA Is product missing from any tank (based upon inventory records)?No Does the facility have power?Yes If no power, a generator?NA Was there any storm damage to facility?Yes Is there water in any tank?No Was there any storm damage to tank systems?No Follow up RequiredYes InspectorZafonte CommentsNo RD; visible signs of contamination; water in the sump; no apparent water in tanks; dispenser repaired; 2' water" Not reported

All Materials:  
Site ID: 478089  
Operable Unit ID: 1227871  
Operable Unit: 01

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material ID: 2225429  
Material Code: 0064A  
Material Name: unknown material  
Case No.: Not reported  
Material FA: Other  
Quantity: .01  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported

RCRA NonGen / NLR:

Date form received by agency: 2007-01-01 00:00:00.0  
Facility name: OCEAN AVENUE GAS CORP  
Facility address: 3010 OCEAN AVE  
BROOKLYN, NY 11235  
EPA ID: NYD986984169  
Mailing address: OCEAN AVE  
BROOKLYN, NY 11235  
Contact: Not reported  
Contact address: OCEAN AVE  
BROOKLYN, NY 11235  
Contact country: US  
Contact telephone: Not reported  
Contact email: Not reported  
EPA Region: 02  
Classification: Non-Generator  
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: STEVEN SCIARRINO  
Owner/operator address: UNKNOWN  
UNKNOWN, NY 99999  
Owner/operator country: US  
Owner/operator telephone: 212-555-1212  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
Owner/Operator Type: Operator  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

Owner/operator name: STEVEN SCIARRINO  
Owner/operator address: UNKNOWN  
UNKNOWN, NY 99999  
Owner/operator country: US  
Owner/operator telephone: 212-555-1212  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
Owner/Operator Type: Owner  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Mixed waste (haz. and radioactive): No  
Recycler of hazardous waste: No  
Transporter of hazardous waste: No  
Treater, storer or disposer of HW: No  
Underground injection activity: No  
On-site burner exemption: No  
Furnace exemption: No  
Used oil fuel burner: No  
Used oil processor: No  
User oil refiner: No  
Used oil fuel marketer to burner: No  
Used oil Specification marketer: No  
Used oil transfer facility: No  
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0  
Site name: OCEAN AVENUE GAS CORP  
Classification: Not a generator, verified

Date form received by agency: 1995-03-29 00:00:00.0  
Site name: OCEAN AVENUE GAS CORP  
Classification: Not a generator, verified

Date form received by agency: 1991-02-25 00:00:00.0  
Site name: OCEAN AVENUE GAS CORP  
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001  
. Waste name: IGNITABLE WASTE

. Waste code: D008  
. Waste name: LEAD

. Waste code: F002  
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004  
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005  
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: NONE  
. Waste name: None

Violation Status: No violations found

US AIRS MINOR:

Envid: 1000555869  
Region Code: 02  
Programmatic ID: AIR NY0000002610700077  
Facility Registry ID: 110010294788  
D and B Number: Not reported  
Primary SIC Code: 5541  
NAICS Code: 999999  
Default Air Classification Code: MIN  
Facility Type of Ownership Code: POF  
Air CMS Category Code: Not reported  
HPV Status: Not reported

US AIRS MINOR:

Region Code: 02  
Programmatic ID: AIR NY0000002610700077  
Facility Registry ID: 110010294788  
Air Operating Status Code: OPR  
Default Air Classification Code: MIN  
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards  
Activity Date: 1989-01-01 00:00:00  
Activity Status Date: Not reported  
Activity Group: Compliance Monitoring  
Activity Type: Inspection/Evaluation  
Activity Status: Not reported

FINDS:

Registry ID: 110010294788  
Facility URL: [http://ofmpub.epa.gov/enviro/fii\\_query\\_detail.disp\\_program\\_facility?p\\_registry\\_id=110010294788](http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110010294788)

Environmental Interest/Information System:

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act. RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.  
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.  
AIR MINOR

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000555869
Registry ID:	110010294788
DFR URL:	<a href="http://echo.epa.gov/detailed-facility-report?fid=110010294788">http://echo.epa.gov/detailed-facility-report?fid=110010294788</a>
Name:	OCEAN AVENUE GAS CORP
Address:	3010 OCEAN AVE
City,State,Zip:	BROOKLYN, NY 11235